

FIG 1




FIG 2




FIG 3




FIG 4




FIG 5

.

.

5/18

Bit 1	m m-1 3 2 1 0	Bit 0 of Parity Block =	Bit 0 of Data Block 1 XOR Bit 0 of Data Block 2 XOR
	Data Block 1		
	Data Block 2		Bit 0 of Data Block N XOR
	•	. Bit m of Parity Block =	Bit m of Data Block 1 XOR
	Data Block N	·	Bit m of Data Block 2 XOR
	Parity Block		Bit m of Data Block N XOR

FIG 6

Bit n	Data Block 1 Data Block 2 Lost !!	Bit 0 of Data Block 2 = Bit 0 of Data Block 1 XOR Bit 0 of Data Block 3 XOR Bit 0 of Data Block N XOR
	Data Block N	Bit m of Data Block 2 = Bit m of Data Block 1 XO Bit m of Data Block 3 XO .
	Parity Block	Bit m of Data Block N XOR

FIG 7




FIG 8




FIG 9




FIG 10




FIG 11




FIG 12

11/18




FIG 13




FIG 14

13/18




FIG 15

14/18




FIG 16

15/18




FIG 17

16/18




FIG 18

17/18




FIG 19




FIG 20